Work Order ID 6064	łO
--------------------	----



Page 1

Thursday, July 1	5, 2010 11:3	4:26 AM									
Item ID: Revision ID: Item Name:	D3947-2 Panel, Upper R	LH Post		Accept				s s	Setup Star Stop		
	7/15/2010	Start Qty: 1.00 Req'd Qty: 1.00			Cust Item l Customer:	ID:			·	1 188111181 8	1818 118 118 <b>1 1881</b>
Approvals:	Process Pla	n: //	Date:	Tooling: SPC (Y/N):		ate:		F	Run Star Stop		8118
Sequence ID/ Work Center II	)	Operation Description		Set Up/ Run Hours	Tool ID	Tool#	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Rev	ision Nbr									**************************************
D3947	A		1								
Hand Finishing The	rmoforming	HAND FINISHING THE Memo  Cut Blank	HERMOFORMING s to fit frame size	0.00						(	10/07/5
Hand Finishing The	rmoforming	Dry Material  Memo Dry Sheet  Temp: Time IN:	as per QSI022 POLYCAR  240 F  4:30 PM	0.00 0.00 BONATE			4				
		Time OUT	΄ Ο ΄ - λ	10/07/19						(x1	) <del>       </del> 

	-										
W/O:				WC	ORK ORDER CHANG	ES					
DATE	STEP		PRO	OCEDURE CHA	NGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
					W-404					<del></del>	
<u></u>											
Part No:			PAR #:	Fault Cate	gory:	_ NCR:	Yes N	lo DQ/	<b>4</b> :	_ Date: _	
	Re	esolutio			n:					Date:	
NCR:			,	WORK ORD	ER NON-CONFORMA	ANCE (	NCR)				
DATE	STEP		Description of NC		Corrective Action Section		\! 0	Verific	ation	Approval	Approval
•	ĺ		Section A	Initial Chief Eng	Action Description  Chief Eng		Sign & Date	Secti	on C	Chief Eng	QC Inspector
1 , 1										t	
			<u> </u> 								
					· · · · · · · · · · · · · · · · · · ·	-					
,	. /				·						
. *	?										
										:	

	der ID 60 215, 2010 11:.										Page 2
Item ID: Revision ID: Item Name: Start Date: Required Date Reference:	D3947-2 Panel, Upper 7/15/2010 e: 7/22/2010	RH Post  Start Qty: 1.00  Req'd Qty: 1.00	i 188181 (181) 180) I 188181 (181) 180)	Accept	Cust Item I				Setup	Start Stop	
Approvals:	Process Pla	n:	Date:	Tooling: SPC (Y/N):		nte:	-		Run	Start Stop	
Sequence ID/ Work Center 1 110	ID	Operation Description	44.000	Set Up/ Run Hours 0.00	Tool ID	Tool #	Plan Code	Accept Qty	Reje Qty		Reject Insp. Jumber Stamp
Thermoform Thermoforming Ma	achine	THERMOFORMING N  Memo  1-Machine  2-Pre-heat 1	Set-up	0.00						(	10/0d19
		Folio Rev.	orm asper Dwg. D36476-1	and Folio FTA 045 using	g tool DT9483 [						
QC Quality Control	4	QC2- Inspect parts off m  Memo  Visually ins	nachine FAI/FAIB  pect for proper formation of	0.00 0.00 f each part						(	(प्रेगीप.
QC Quality Control		QC8- Inspect parts - seco	ond check	0.00						(	D B001,19

#### **Dart Aerospace Ltd** W/O: **WORK ORDER CHANGES Approval Approval** DATE **STEP PROCEDURE CHANGE** By Date Qty Chief Eng / QC Inspector Prod Mgr Part No: \_\_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_ Date: \_\_\_\_ Resolution: \_\_\_\_\_ Disposition: \_\_\_\_\_ QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_ **WORK ORDER NON-CONFORMANCE (NCR)** NCR: **Corrective Action** Section B Description of NC Verification **Approval Approval** DATE **STEP** Sign & **Action Description** Initial Section A Section C Chief Eng QC Inspector Date Chief Eng Chief Eng

Work Ord Thursday, July												Page 3
Item ID: Revision ID: Item Name: Start Date: Required Date: Reference:	D3947-2 Panel, Upper I 7/15/2010 : 7/22/2010	RH Post  Start Qty: 1.00  Req'd Qty: 1.00			Cust Iter	n ID:			Setup	Start		18
Approvals:	Process Pla	n:	Date:	Tooling:		Date:			Run	Start		
	QC:	<u>'</u>	Date:	SPC (Y/N):		Date:				Stop		
Sequence ID/ Work Center II	D	Operation Description		Set Up/ Run Hours	Tool ID	Tool#	Plan Code	Accep Qty	t Rej Qty		Reject Number	Insp. Stamp
Thomas		HAND FINISHING TH	ERMOFORMING	0.00		:	3040	Q.ij	Qij	,	()(I)	Stamp /
Thermoform Thermoforming Ma	chine	<b>Memo</b> Trim to Fini	shed Dimensions as per	dwg D3946-1		:					30	# 10/07/21
150		QC2- Inspect parts off m	achine FAI/FAIB	0.00								/ /
QC Quality Control		Memo Check dime	nsions to ensure conform	0.00 nity to drawing tolerances.								B10/07/
160 QC Quality Control		QC5- Inspect part compl  Memo	eteness to step on W/O	0.00 S volum	<del>)</del>		4	@				
!												

	•		•							
W/O:				W	ORK ORDER CHANG	ES				
DATE	STEP		PRO	OCEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	•		PAR #:	Fault Cate	gory:	NCR: Yes	No <b>DQ</b>	A:	Date: _	
	Re	esolutio	n:	Dispositio	n:	QA: N/C Cld	osed:		Date: _	
NCR:				WORK ORD	ER NON-CONFORMA	NCE (NCR	)			
DATE	STEP		Description of NC		Corrective Action Section		Verifi	cation	Approval	Approval
DAIL	JILF		Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Sec	tion C	Chief Eng	QC Inspector
r										
				ļ						
							-			-
			•							

Work	Order	ID	60646
Thursday	July 15	2010	11.34.2



Page 4

Revision ID: Item Name:	D3947-2 Panel, Upper	RH Post		Accept				Setup	Start Stop	
Start Date: Required Date: Reference:	7/15/2010 7/22/2010	Start Qty: 1.00 Req'd Qty: 1.00			Cust Item ID Customer:	:			STOP	
Approvals:	Process Pla	an:	Date:	Tooling: SPC (Y/N):	Date			Run	Start Stop	
Sequence ID/ Work Center II 170 Packaging Packaging	)	Operation Description Identify as per dwg & St	cock Location:	Set Up/ Run Hours 0.00	Tool ID	Tool # Plan Cod		t Rej Qty $1/\sqrt{2}$		Reject Insp. Number Stamp
180 QC		QC21- Final Inspection -	· - Work Order Release	0.00			-			107/28 \$
Quality Control	4		; () ()	•	•			H	(0/	

	_										
W/O:				W	ORK ORDER CHANG	GES				<del>, , , , , , , , , , , , , , , , , , , </del>	
DATE	STEP		PRO	OCEDURE CHA	NGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		i									
					•						
Part No	:		PAR #:	Fault Cate	egory:	NCF	R: Yes	No DQ	A:	Date: _	
	R	esolutio	h:	Disposition	on:	QA:	N/C Clo	sed:		Date: _	
NCR:				WORK ORD	ER NON-CONFORM	IANCE	(NCR)	)		· · ·	
DATE	CTED		Description of NC			ction B		Verific	cation	Approval	Approval
DATE	STEP		Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date		ion C	Chief Eng	QC Inspector
											: 1
	İ			i.							
						ı					

### **Picklist Print**

Thursday, July 15, 2010 11:34:30 AM

Work Order ID: 60646

Parent Item: D3947-2

Parent Item Name: Panel, Upper RH Post

**Start Date:** 7/15/2010

Required Date: 7/22/2010

Start Qty: 1.00

Required Qty: 1.00

Comments:

IPP RevA: New issue DD verified by:EC

Add Step 105 Dry Material 10/04/21 DL

IPP RevB

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
MLEXS.093-F6006-07		Purchased	No			100	sf	1,876.541	3.3055	3.479474			

GE PLASTICS LEXAN SHEET

 Location
 Loc Oty
 Loc Code

 therm
 1876.541

 107574
 13.72

 30.875
 1112176

 101.2267
 114459

 1730.7193

BE


विवर्गाव

	•		B								
W/O:				W	ORK ORDER CHANG	ES					
DATE	STEP		PRO	OCEDURE CH	ANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
· ···· · ·											
Part No	•		PAR #:	Fault Cat	egory:	_ NCR:	Yes N	o DQA	۸:	Date:	
	R	esolutio	:	Dispositi	on:	_ QA: I	V/C Clos	sed:		Date:	<u> </u>
NCR:		<i>:</i>		WORK ORI	DER NON-CONFORMA	ANCE	(NCR)				
DATE	OTED		Pescription of NC		Corrective Action Section		,.	Verific	ation	Approval	Approval
DATE	STEP		Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Section		Chief Eng	QC Inspector
											·
		i									
									,		

DART AEROSPA	CE LTD	<del></del>		Wo	rk Order:	40416
Description: Panel,	Upper RH			Pa	rt Number:	D3947-2
nspection Dwg: D3	947 <b>Rev</b> : A					Page 1 of 1
	x	ARTICLE INSF		Prototy		
Description	Т	HERMOFORM	Accept	CTION Reject	Method of	Comments
			_		Inspection	
nside Radii less than Shape Definition	<u>"</u>					
Fexture Retention					-	The second secon
Material imperfections cratching	s such as bumps	cracks, voids,				
Measured by:	B				Date:	10/07/2/
		TRIMMING	SECTIO	N		
Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
10.0	Min	10.25	~			
0.2	Min	.304				
	Min	.542				
0.5						
1.8	Min	1.836				
1.8	REF	1.836				
1.8 3.1 26.6	REF REF	3.5				
1.8 3.1 26.6 0.050	REF REF Min	3.5				
1.8 3.1 26.6	REF REF	3.5	~			
1.8 3.1 26.6 0.050	REF REF Min	3.5 R6.675 .083	レレ			
1.8 3.1 26.6 0.050 0.070	REF REF Min Min	3.5 R6.675 .083	レレ			
1.8 3.1- 26.6 0.050 0.070 Measured by:	REF REF Min Min	3.5 R6.675 .083	レレ		Date:	10/07/21
1.8 3.1 26.6 0.050 0.070	REF REF Min Min	3.5 24,675 ,083 ,073	レレ		Date: Date:	


09.09.15 New Issue

W/O:			٧	VORK ORDER CHANGE	ES							
DATE	STEP	PRO	CEDURE CH	IANGE	By Date				Approval Chief Eng / Prod Mgr	Approval QC Inspector		
					_							
								<u> </u>				
									Ī			
		i										
Part No	•	PAR #:	Fault Ca	tegory:	NCR:	Yes I	No DQA:	_	Date:			
	R	esolution:		•					Date:			
NCR:		<b>\</b>	WORK OR	DER NON-CONFORMA	NCE (	NCR)	)					
DATE	STEP	Description of NC	Corrective Action Section B Initial Action Description			Sign &	Verificat		Approval	Approval		
		Section A	Chief Eng	Action Description Chief Eng	•	Date	Section		Chief Eng	QC Inspector		
	,							İ				
							·					
							-					
			ļ									
	1	1	ı	1	I		1		1	1		




#### **Dart Aerospace Ltd WORK ORDER CHANGES** W/O: **Approval Approval** By Qty **PROCEDURE CHANGE** DATE **STEP** Date Chief Eng / QC Inspector Prod Mgr Part No: \_\_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_ Date: \_\_\_\_ Resolution: \_\_\_\_\_ Disposition: \_\_\_\_ QA: N/C Closed: \_\_\_\_ Date: \_\_\_\_ **WORK ORDER NON-CONFORMANCE (NCR)** NCR: **Corrective Action** Section B Verification Description of NC **Approval Approval** DATE **STEP** Sign & **Action Description** Initial Section A Section C Chief Eng QC Inspector


	i		Chief Eng	Chief Eng	Date			
						,	'	
	1	l l						
			İ					
				:				
	İ		-					
	<del></del>		 			<del></del> .	"	
		I						
							İ	
								·
					1			,
	Į	ı						
	f	1						
	7721					-	,	
		ı				!		
ļ								
			1					
			<u> </u>					



Dart Ae	rospace l	Ltd										
W/O:				WO	RK ORDER CHANGES	3						
DATE	STEP		PRO	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector				
Part No	):		PAR #:	Fault Cate	gory:	NCR: Yes	No <b>DQ</b>	A:	Date: _			
Resolution:			n:	Disposition	n:	QA: N/C Closed: Date: _						
NCR:			WORK ORDER NON-CONFORMANCE (NCR)									
DATE	STEP	Description of NC	Corrective Action Section B			Verifi	rification Appr		Approval			
DATE	SIEP	<u>.</u>	Section A	Initial Chief Eng	Action Description Chief Eng	Sign of Date	🙎   Sect	tion C	Chief Eng	QC Inspecto		
		:										
			1									



	•									, · · · · ·
W/O:		<del></del>		W	ORK ORDER CHANG	ES				
DATE STEP			PRO	OCEDURE CH	ANGE	Ву	Date	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
									r rod mgr	
									•	
Part No:			PAR #:	Fault Cat	_ NCR: Yes	No <b>DQA</b>	i:	Date:		
		esolutio	h:	Disposition:				_ QA: N/C Closed:		
NCR:			,	WORK ORE	DER NON-CONFORMA	ANCE (NCR	)			
DATE STEP			Description of NC		ion B	Verifica	ation	Approval	Approval	
DAIL	SILF		Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Sectio	n C	Chief Eng	QC Inspector
										!
							i			
									:	
										<u>[</u>
	1					1	1		1	



Duit Aciospace Eta	Dart	Aeros	pace	Ltd
--------------------	------	-------	------	-----

	•		1											
W/O:			WORK ORDER CHANGES											
DATE	STEP		PRO	CEDURE CH	CEDURE CHANGE			Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
								,						
		<del> </del>												
											•.			
							į							
			PAR #: Fault Category: NO					NCR: Yes No DQA: Date:						
		esolutio	n:	Disposition: Q				osed:		Date: _				
NCR:			\	WORK ORE	DER NON-CONFORM	ANCE	(NCR	)						
DATE STEP			Description of NC	Corrective Action Section B			———— verifica			Approval	Approval			
DAIL	SILP		Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Sect	ion C	Chief Eng	QC Inspector			
				40.										
								:						